

An aerial photograph of an industrial facility. In the foreground, a large, white, rectangular building with a flat roof is prominent. Behind it, a dark-colored building with a gabled roof is visible. To the left of the dark building, a tall, white water tower stands out against the green trees. The site is surrounded by dense green foliage. Several vehicles are parked in a lot on the left side of the image. The text "Detail of Etching Building" is overlaid in yellow at the top, and "Safety Light Corp. Site Bloomsburg PA" is overlaid in yellow at the bottom. A small, faint text "Photo From Internet" is visible in the bottom right corner.

Detail of Etching Building

**Safety Light Corp. Site
Bloomsburg PA**

Photo From Internet

An aerial photograph of an industrial facility. In the foreground, a large, white, rectangular building with a flat roof is prominent. Behind it, a dark-colored building with a gabled roof is visible. To the left of the dark building, a tall, white water tower stands out against the green trees. The site is surrounded by dense green foliage. Several vehicles are parked in a lot on the left side of the image. The text "Detail of Etching Building" is overlaid in yellow at the top, and "Safety Light Corp. Site Bloomsburg PA" is overlaid in yellow at the bottom. A small, faint text "Photo From Internet" is visible in the bottom right corner.

Detail of Etching Building

**Safety Light Corp. Site
Bloomsburg PA**

Photo From Internet

Conestoga River

Old House

Old House
Processing Structure

Existing Building

Trillium Building

Main Building

Old House's
Station

Safety Light Corporation Site
Bloomsburg, PA

Photo: Press Enterprise

Conestoga River

Old House

Old House
Processing Structure

Existing Building

Trillium Building

Main Building

Old House's
Station

Safety Light Corporation Site
Bloomsburg, PA

Photo: Press Enterprise





SEP 30 2003



SEP 30 2003



FEB 26 2004



FEB 26 2004



FEB 26 2004



FEB 26 2004



Rear of Etching Building

FEB 26 2004



Rear of Etching Building

FEB 26 2004



Rear of Etching Building



Rear of Etching Building





DEC 18 2003



DEC 18 2003







MAR 10 2004




MAR 10 2004



CAUTION




CAUTION
RADIOACTIVE MATERIAL
NEEDLE
RADIO
METER



Nurse's Station

Main Building

1/8/2002 10:36



Nurse's Station

Main Building

1/8/2002 10:36



MAR 10 2004



"Old House"

SEP 30 2003



"Old House"

SEP 30 2003



MT

MT
P





MT

MT
P



DIFFUSE WASTE



JARS, VIALS & DIALS



FOILS



CLOCK DIAL



"DECK" MARKERS



LEAD "PIG"



DIFFUSE WASTE



JARS, VIALS & DIALS



FOILS



CLOCK DIAL



"DECK" MARKERS



LEAD "PIG"





MAR 10 2004



MAR 10 2004



Pipe Shop

FEB 26 2004



Pipe Shop

FEB 26 2004



A photograph of a room in a state of severe disrepair and contamination. The floor is covered in debris, including wood shavings and dust. In the center, there is a white metal stand with a glass-enclosed piece of equipment on top, which appears to be a fume hood or a similar laboratory device. To the left of this stand is a yellow metal drum, and in the foreground, another yellow metal drum is visible. The background shows a doorway leading to another area, and the walls are peeling and damaged. The overall scene suggests a hazardous waste site or a laboratory that has been abandoned or is in the process of being dismantled.

Contaminated Equipment

**Radioactive
Waste Drums**

FEB 26 2004

Radium Screening Room- Safety Light Site

A photograph of a room in a state of significant disrepair and contamination. The floor is covered in debris, including wood shavings and dust. In the center, there is a white metal stand with a glass-enclosed piece of equipment on top, which appears to be a fume hood or a similar laboratory device. To the left of this stand is a yellow metal drum, and in the foreground, another yellow metal drum is visible. The background shows a doorway leading to another area, and the walls are peeling and damaged. The overall scene suggests a hazardous waste site or a laboratory that has been abandoned or is in the process of being dismantled.

Contaminated Equipment

**Radioactive
Waste Drums**

FEB 26 2004

Radium Screening Room- Safety Light Site

A photograph of a dilapidated concrete structure, identified as the Radium Vault. The structure is made of grey concrete blocks and has a large section of its outer wall missing, revealing a lighter interior. A yellow radiation warning sign is mounted on the remaining wall. To the left, there are wooden utility poles with wires. To the right, a white building with a dark door is visible. The ground is covered in green grass. The sky is blue with some clouds. The text "Radium Vault" is overlaid in yellow with a black outline. In the bottom right corner, there is a red timestamp "30 12:23 PM".

Radium Vault


30 12:23 PM



Radium Vault

30 12:23 PM









Tritium Vent Stack

Tritium Building

**Nuclear
Machine Shop**



Tritium Vent Stack

Tritium Building

**Nuclear
Machine Shop**





West Dump

OCT 22 2003



OCT 22 2003

West Dump